Slip Test Report – Batch Certification

National Ceramic Industries Australia Pty Ltd, ABN: 83 100 467 267					
175 Racecourse Rd, Rutherford NSW 2320, Australia, Tel: +61 2 4931 8400 Fax: +61 2 4931 8499, www.ncia.com.au					
Slip Resistance Classification of New Pedestrian Surfaces Materials Australia Standard AS 4586:2013 Appendix A (Wet Pendulum Test Method)					
Production Date	03/04/2023	**Test Sheet No:**	230403	**Issue Date**	27/07/2023
Tile Name/s	Kensington Grey P3 300x300	**Code/s**	ZKN62522A	**Batch**	6043

Testing was conducted using a 96 rubber slider in accordance with the above Standard.
Slider was prepared/conducted using P400C paper and 3 µm lapping film

Reference	**Test Location**	**Cleaning Pre-testing**	**Results of Last three Swings British Pendulum Number (BPN)**			**Mean BPN**	**Classification of Pedestrian Surfaces Materials according to the above Standard**
ZKN62522A	Tile Surface	Water & Scrubbing	Recorded	Recorded	Recorded	38	**P3**
Temperature (indoor)	21.8°C	Mean BPN Slip Resistance Value (SRV)				38	
Testing Instrument	Pendulum Friction Tester, Calibration Date: 03 November 2022				National Ceramic Industries Australia Pty Ltd		
Testing Officer	Luke Crisp				NCIA Tiles Testing Laboratory		
					Controlled Document version 1		

stoneworld
NATIONWIDE TILES & SURFACES

1st August 2023

TO WHOM IT MAY CONCERN

Re : SLIP RESISTANCE CLASSIFICATION REPORT – Kensington 300 x 300 Matt

Dear Sir / Madam,

Please find attached the Slip Resistance Classification Report for the Stoneworld tile, Kensington 300 x 300 Matt.

Please be aware that the attached test results are from the batch of tiles that were available at the time of testing. These test results are provided as an indication of slip rating as the slip rating may vary for each batch of tiles. Stoneworld provides slip rating test results as a guide ONLY and takes no responsibility for the slip rating of any non-tested batches, nor is it liable for any costs incurred in any further testing or re-testing of tiles.

The test result of tiles may change subsequent to delivery, through the laying process, during the completion of the building work, or through wear and tear.

Regards,

Alan Williams

GROUP NATIONAL MANAGER

10 YEAR WARRANTY